

Training Center

Clackamas CC

Clac_coc07A

Building Type	County	
Community_College	Clackamas	
Street		
19600 S. Molalla Avenue		
City	State	Zip
Oregon City	OR	97045
Latitude	Longitude	
45.32556	122.56657	
Tracking Code	Inspection Date	
New Building	3/1/2007	

No Photo Available

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Training Center

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text" value="1994"/>	<input type="text" value="1994"/>	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
<input type="text" value="18385"/>	<input type="text" value="1"/>	<input type="text" value="No"/>	<input type="text" value="No"/>

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>