

# Pauling Center - South

Clac\_coc10A

Clackamas CC

|                         |       |                 |  |
|-------------------------|-------|-----------------|--|
| Building Type           |       | County          |  |
| Community_College       |       | Clackamas       |  |
| Street                  |       |                 |  |
| 19600 S. Molalla Avenue |       |                 |  |
| City                    | State | Zip             |  |
| Oregon City             | OR    | 97045           |  |
| Latitude                |       | Longitude       |  |
| 45.32226                |       | 122.57356       |  |
| Tracking Code           |       | Inspection Date |  |
| RVS in 2006             |       | 9/22/2006       |  |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | -1         | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 0.9       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Pauling Center - South

## Final RVS Score

Final Type


Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Pauling Center - South

Clac\_coc10A

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        | 1981                        | 1981                     | 1980               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
| 40430                  | 1                           | No                       | Yes                |

|                                    |                                         |
|------------------------------------|-----------------------------------------|
| Plan Irregularities                | Vertical Irregularities                 |
| Reentrant Corners: Other           | Steps in Elevation View: 2 to 3 Changes |
| Large Diaphragm or Central Opening | None                                    |
| None                               | None                                    |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |



# Pauling Center - East

Clackamas CC

Clac\_coc10B

|                         |                 |           |  |
|-------------------------|-----------------|-----------|--|
| Building Type           |                 | County    |  |
| Community_College       |                 | Clackamas |  |
| Street                  |                 |           |  |
| 19600 S. Molalla Avenue |                 |           |  |
| City                    | State           | Zip       |  |
| Oregon City             | OR              | 97045     |  |
| Latitude                | Longitude       |           |  |
| 45.32226                | 122.57356       |           |  |
| Tracking Code           | Inspection Date |           |  |
| RVS in 2006             | 9/22/2006       |           |  |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | -1         | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 0.9       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Pauling Center - East

## Final RVS Score

Final Type


Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



# Pauling Center - East

Clac\_coc10B

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        | 1981                        | 1981                     | 1980               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
|                        | 1                           | No                       | Yes                |

|                                    |                                         |
|------------------------------------|-----------------------------------------|
| Plan Irregularities                | Vertical Irregularities                 |
| Reentrant Corners: Other           | Steps in Elevation View: 2 to 3 Changes |
| Large Diaphragm or Central Opening | None                                    |
| None                               | None                                    |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |



NW Plan Irregularity Primary



W Elevation View



SW Plan Irregularity Primary



SE Plan Irregularity Primary



E Vertical Irregularity Primary



NE Elevation View



NE Elevation View



NW Elevation View



W Pounding Potential