

Roger Rook Hall

Clackamas CC

Clac_coc17A

Building Type		County	
Community_College		Clackamas	
Street			
19600 S. Molalla Avenue			
City	State	Zip	
Oregon City	OR	97045	
Latitude		Longitude	
45.32227		122.57427	
Tracking Code		Inspection Date	
New Building		3/1/2007	

No Photo Available

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Roger Rook Hall


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2003	2003	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
30000	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions