

Hoodland RFPD 74

Clac_fir05A

Hoodland RFPD

| | | |
|-------------------------------|------------------------------|--------------|
| Building Type Fire - RFPD | County Clackamas | |
| Street 69634 E Hwy 26 | | |
| City Welches | State OR | Zip 97067 |
| Latitude 45.34437 | Longitude 121.94813 | |
| Tracking Code Hasenberg 02 | Inspection Date 9/15/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W1 | 5.2 | 0 | 0 | 0 | 0 | 0 | -0.6 | 0 | 4.6 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Hoodland RFPD 74

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1 | 4.6 |

FEMA-154 Collapse Potential

Low (<1%)

Hoodland RFPD 74

Clac_fir05A

| | | | |
|--|-----------------------------|---|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | 1970 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 8850 | 1 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |
|  | |  | |
| S | General Site | S | General Site |