

# CCFD Fire Station 6 Happy Valley

Clac\_fir13A

Clackamas Co Fire Dist #1

Building Type		County	
Fire - RFPD		Clackamas	
Street			
12900 Se King Rd			
City	State	Zip	
Portland	OR	97236	
Latitude	Longitude		
45.44735	122.53078		
Tracking Code	Inspection Date		
Hasenberg 02	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

CCFD Fire Station 6 Happy Valley

## Final RVS Score

Final Type

Final Score

W1

4.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# CCFD Fire Station 6 Happy Valley

Clac\_fir13A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1970	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
4620	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site