

Molalla RFPD 73

Clac_fir16A

Molalla RFPD

Building Type		County	
Fire - RFPD		Clackamas	
Street			
27689 S Hwy 213			
City	State	Zip	
Mulino	OR	97042	
Latitude		Longitude	
45.20631		122.58166	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Molalla RFPD 73

Final RVS Score

Final Type

Final Score

RM1

2.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1970	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3600	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions

