

# Molalla RFPD 73

Clac\_fir17A

Molalla RFPD

Building Type	County	
Fire - RFPD	Clackamas	
Street		
36715 S Sawtell Rd		
City	State	Zip
Molalla	OR	97038
Latitude	Longitude	
45.07475	122.55499	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Molalla RFPD 73

## Final RVS Score

Final Type

Final Score

W1

4.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1970	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2560	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions