

# Molalla RFPD 73

Clac\_fir18A

Molalla RFPD

Building Type		County	
Fire - RFPD		Clackamas	
Street			
320 N Molalla Ave			
City	State	Zip	
Molalla	OR	97038	
Latitude		Longitude	
45.15029		122.57699	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Molalla RFPD 73

## Final RVS Score

Final Type

Final Score

W2

3.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1967	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
11800	1	No	No

  

Plan Irregularities	Vertical Irregularities

  

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site