

TVF & R - Station 57 Mountain Rd

Clac_fir20A

Tualatin Valley F&R

Building Type		County	
Fire - RFPD		Clackamas	
Street			
24242 Sw Mountain Rd			
City	State	Zip	
West Linn	OR	97068	
Latitude	Longitude		
45.3448	122.708		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 57 Mountain Rd

Final RVS Score

Final Type

Final Score

S3

3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	1995	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3600	1	No	No

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

