

# Lake Oswego Fire Department

City of Lake Oswego

Clac\_fir21A

Building Type		County	
Fire - City		Clackamas	
Street			
4900 Melrose St			
City	State	Zip	
Lake Oswego	OR	97035	
Latitude		Longitude	
45.42576		122.72492	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lake Oswego Fire Department

## Final RVS Score

Final Type

Final Score

W2

5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1988	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6650	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site