

# CCFD Fire Station 3 Oak Lodge

Clac\_fir27A

Clackamas Co Fire Dist #1

Building Type		County	
Fire - RFPD		Clackamas	
Street			
2930 Se Oak Grove Blvd			
City	State	Zip	
Milwaukie	OR	97267	
Latitude	Longitude		
45.41529	122.63295		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

CCFD Fire Station 3 Oak Lodge

## Final RVS Score

Final Type

Final Score

W2

5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1996	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
19400	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions