

Hoodland RFPD 74

Clac_fir31A

Hoodland RFPD

Building Type		County	
Fire - RFPD		Clackamas	
Street			
61388 E Hwy 26			
City	State	Zip	
Brightwood	OR	97011	
Latitude	Longitude		
45.37534	122.0329		
Tracking Code	Inspection Date		
Hasenberg 02	9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoodland RFPD 74

Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1970	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2200	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions