

TVF & R - Station 58 Bolton

Clac_fir32A

Tualatin Valley F&R

Building Type		County	
Fire - RFPD		Clackamas	
Street			
6050 Failing St			
City	State	Zip	
West Linn	OR	97068	
Latitude	Longitude		
45.37071	122.62218		
Tracking Code	Inspection Date		
To be Re-built	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 58 Bolton

Final RVS Score

Final Type

Final Score

W1

4.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 58 Bolton

Clac_fir32A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1950	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5600	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site