

Sandy FFPD 72

Sandy FFPD

Clac_fir37A

| | | |
|-------------------------------|------------------------------|--------------|
| Building Type Fire - RFPD | County Clackamas | |
| Street 17460 Bruns Ave | | |
| City Sandy | State OR | Zip 97055 |
| Latitude 45.3966 | Longitude 122.26367 | |
| Tracking Code Hasenberg 02 | Inspection Date 9/15/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 3.6 | 0 | 0 | 0 | 0 | -0.8 | 0 | 0 | 2.8 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Sandy FFPD 72

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 2.8 |

FEMA-154 Collapse Potential

Low (<1%)

| | | | |
|--|-----------------------------|---|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | 1965 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 11700 | 2 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |
|  | |  | |
| S | General Site | S | General Site |
| S | General Site | S | General Site |