

# Canby Fire District 62

Canby RFPD

Clac\_fir39A

Building Type Fire - RFPD	County Clackamas	
Street 221 S Pine St.		
City Canby	State OR	Zip 97013
Latitude 45.26451	Longitude 122.68271	
Tracking Code New Building	Inspection Date 9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canby Fire District 62

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)

# Canby Fire District 62

Clac\_fir39A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	1996	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13800	1	No	No
Plan Irregularities		Vertical Irregularities	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
Falling Hazards		Poor Conditions	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
			
S	General Site	S	General Site