

Sandy FFPD 72

Clac_fir43A

Sandy FFPD

Building Type	County		
Fire - RFPD	Clackamas		
Street			
24545 SE Firwood Rd			
City	State	Zip	
Sandy	OR	97055	
Latitude	Longitude		
45.34564	122.23576		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	1.6	0	-0.6	0	6.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sandy FFPD 72

Final RVS Score

Final Type

Final Score

W1

6.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1995	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
4400	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site

