

CCFD Fire Station 17 South End

Clac_fir51A

Clackamas Co Fire Dist #1

Building Type		County	
Fire - RFPD		Clackamas	
Street			
19001 South End Rd			
City	State	Zip	
Oregon City	OR	97045	
Latitude	Longitude		
45.33227	122.62561		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

CCFD Fire Station 17 South End

Final RVS Score

Final Type

Final Score

W2

5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2002	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7300	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions

