

TVF & R - Station 358 Rosemont

Tualatin Valley F&R

Clac_fir52A

Building Type Fire - RFPD	County Clackamas								
Street 1000 Station Lane									
City West Linn	State OR		Zip 97068						
Latitude 45.38244	Longitude 122.66537								
Tracking Code Hasenberg 02	Inspection Date 9/15/2006								
Seismicity Zone: High									
FEMA 154 Rapid Visual Screening Score Card									
Type	Basic Score		Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E
Primary	C2	2.8	0	0	0	0	0	0	2.8
Secondary	0	0	0	0	0	0	0	0	0
Tertiary	0	0	0	0	0	0	0	0	0

TVF & R - Station 358 Rosemont

Final RVS Score

Final Type	Final Score
C2	2.8

FEMA-154 Collapse Potential

Low (<1%)

TVF & R - Station 358 Rosemont

Clac_fir52A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1950	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6500	2	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



S General Site