

<table style="width: 100%; border-collapse: collapse;"><tr><td style="width: 30%;">Building Type</td><td style="width: 30%;">County</td><td style="width: 40%;"></td></tr><tr><td><input type="text" value="Fire - RFPD"/></td><td><input type="text" value="Clackamas"/></td><td></td></tr><tr><td colspan="3">Street</td></tr><tr><td colspan="3"><input type="text" value="8455 SW Elligsen Road"/></td></tr><tr><td>City</td><td>State</td><td>Zip</td></tr><tr><td><input type="text" value="Wilsonville"/></td><td><input type="text" value="OR"/></td><td><input type="text" value="97070"/></td></tr><tr><td>Latitude</td><td colspan="2">Longitude</td></tr><tr><td><input type="text"/></td><td colspan="2"><input type="text"/></td></tr><tr><td>Tracking Code</td><td colspan="2">Inspection Date</td></tr><tr><td><input type="text" value="To Be Rebuilt"/></td><td colspan="2"><input type="text" value="3/1/2007"/></td></tr></table>	Building Type	County		<input type="text" value="Fire - RFPD"/>	<input type="text" value="Clackamas"/>		Street			<input type="text" value="8455 SW Elligsen Road"/>			City	State	Zip	<input type="text" value="Wilsonville"/>	<input type="text" value="OR"/>	<input type="text" value="97070"/>	Latitude	Longitude		<input type="text"/>	<input type="text"/>		Tracking Code	Inspection Date		<input type="text" value="To Be Rebuilt"/>	<input type="text" value="3/1/2007"/>		<h1 style="font-size: 2em; margin: 0;">No Photo Available</h1>
Building Type	County																														
<input type="text" value="Fire - RFPD"/>	<input type="text" value="Clackamas"/>																														
Street																															
<input type="text" value="8455 SW Elligsen Road"/>																															
City	State	Zip																													
<input type="text" value="Wilsonville"/>	<input type="text" value="OR"/>	<input type="text" value="97070"/>																													
Latitude	Longitude																														
<input type="text"/>	<input type="text"/>																														
Tracking Code	Inspection Date																														
<input type="text" value="To Be Rebuilt"/>	<input type="text" value="3/1/2007"/>																														

  

Seismicity Zone: High										
<b>FEMA 154 Rapid Visual Screening Score Card</b>										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary										
Secondary										
Tertiary										

  

TVF & R - Station #56 Elligsen Rd	
<b>Final RVS Score</b>	
Final Type	Final Score
<input type="text"/>	<input type="text"/>
<b>FEMA-154 Collapse Potential</b>	
<input type="text"/>	



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	1979	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
16780	<input type="text"/>	No	No

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

