

Lake Oswego Police Dept

City of Lake Oswego

Clac_pol02A

Building Type	County
EOC-Public Safety Answering P	Clackamas
Street	
380 A Ave	
City	State Zip
Lake Oswego	OR 97034
Latitude	Longitude
45.41944	122.66768
Tracking Code	Inspection Date
Hasenberg 02	9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lake Oswego Police Dept

Final RVS Score

Final Type	Final Score
RM2	2.4

FEMA-154 Collapse Potential

Low (<1%)

Lake Oswego Police Dept

Clac_pol02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1987	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
55000	3	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries