

West Linn Police Dept

City of West Linn

Clac_pol06A

Building Type Police-City	County Clackamas	
Street 22825 Willamette Dr		
City West Linn	State OR	Zip 97068
Latitude 45.36006	Longitude 122.61094	
Tracking Code Hasenberg 02	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	0	0	-0.2	0	0	0	0	1.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Linn Police Dept

Final RVS Score


Final Type	Final Score
URM	1.6

FEMA-154 Collapse Potential

Moderate (>1%)

West Linn Police Dept

Clac_pol06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1920	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6600	2	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries