

Gladstone Police Department

City of Gladstone

Clac_pol09A

Building Type Police - City	County Clackamas	
Street 525 Portland Ave		
City Gladstone	State OR	Zip 97027
Latitude 45.38069	Longitude 122.59439	
Tracking Code Hasenberg 02	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	-1	0	0	0	0	1.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Gladstone Police Department

Final RVS Score

Final Type	Final Score
RM1	1.8

FEMA-154 Collapse Potential

Moderate (>1%)

Gladstone Police Department

Clac_pol09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1940	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
11200	2	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site		

Barlow Hall

Clac_coc09A



SE Pounding Potential
CONN TO BLDG?



E Elevation View
N WING



N Vertical Irregularity Tertiary
SC AT WINDOWS, INFILL PANELS BELOW



N Vertical Irregularity Primary
N WING CONN TO CTR



NE Elevation View
N END OF CTR



NW Vertical Irregularity Secondary
2 STORY BOILR RM SPACE IN N END OF CTR



SW Elevation View



W Elevation View



W Elevation View



SW Elevation View



SW Elevation View
S END OF CTR



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries