

Molalla Police Department

City of Molalla

Clac_pol10A

Building Type Police - City	County Clackamas	
Street 117 N Mollala Ave		
City Molalla	State OR	Zip 97038
Latitude 45.14768	Longitude 122.5767	
Tracking Code Hasenberg 02	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Molalla Police Department

Final RVS Score

Final Type	Final Score
C2	2.4

FEMA-154 Collapse Potential

Low (<1%)

Molalla Police Department

Clac_pol10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1950	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3300	1	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries