

Hallinan Elementary School

Lake Oswego SD 7J

Clac_sch05A

Building Type	County		
School	Clackamas		
Street			
16800 Hawthorne Dr			
City	State	Zip	
Lake Oswego	OR	97034	
Latitude	Longitude		
45.40443	122.66442		
Tracking Code	Inspection Date		
Structural Engineering Report	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hallinan Elementary School

Final RVS Score

Final Type

Final Score

W2

3.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
340		1981	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
46144	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions