

# Uplands Elementary School

Lake Oswego SD 7J

Clac\_sch08A

Building Type		County	
School		Clackamas	
Street			
2055 Wembley Park Rd			
City	State	Zip	
Lake Oswego	OR	97034	
Latitude		Longitude	
45.42138		122.70235	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Uplands Elementary School

## Final RVS Score

Final Type

Final Score

W2

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Uplands Elementary School

Clac\_sch08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
451		1961	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
59136	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site