

Lake Oswego Junior High School

Lake Oswego SD 7J

Clac_sch10A

Building Type School	County Clackamas	
Street 2500 Country Club Rd		
City Lake Oswego	State OR	Zip 97034
Latitude 45.42723	Longitude 122.70215	
Tracking Code Structural Engineering Report	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lake Oswego Junior High School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)

Lake Oswego Junior High School

Clac_sch10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
592		1956	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
106474	1	No	No

Plan Irregularities

Vertical Irregularities

Falling Hazards

Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries