

Waluga Junior High School

Lake Oswego SD 7J

Clac_sch11A

Building Type	County
School	Clackamas
Street	
4700 Jean Rd	
City	State Zip
Lake Oswego	OR 97035
Latitude	Longitude
45.39594	122.72555
Tracking Code	Inspection Date
Structural Engineering Report	9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Waluga Junior High School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)

Waluga Junior High School

Clac_sch11A

Enrollment 549	Year Built (Field Verified) 1964	Year Built (Alt. Source) 1964	Est. Decade Built
Total Area (square ft) 99742	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
Falling Hazards		Poor Conditions	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries