

Linwood Elementary School

North Clackamas SD 12

Clac_sch19A

Building Type School	County Clackamas	
Street 11909 SE Linwood Ave		
City Milwaukie	State OR	Zip 97222
Latitude 45.43641	Longitude 122.59998	
Tracking Code RVS in 2006	Inspection Date 9/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	-0.4	0	0	-0.1
Secondary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Linwood Elementary School

Final RVS Score

Final Type	Final Score
URM	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Linwood Elementary School

Clac_sch19A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
352	1968	1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38622	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
NW Plan Irregularity Primary	SW Vertical Irregularity Primary	SW Secondary Structural Type	THIS END WALL IS WOOD
SW Primary Structural Type TYP BRICKS USED IN WALLS	NW Elevation View	E Primary Structural Type GYM CANOPY WALL	
E Primary Structural Type INNER CANOPY WALL	E Falling Hazard	E Primary Structural Type EAST WALL - 6" BRICK	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Linwood Elementary School

Clac_sch19A



SE Plan Irregularity Primary




E Vertical Irregularity Primary



SE Primary Structural Type
WALL WIDTH



E Primary Structural Type



W Field Verified Year Built



SW Vertical Irregularity Secondary

Linwood Elementary School

North Clackamas SD 12

Clac_sch19B

Building Type School	County Clackamas	
Street 11909 SE Linwood Ave		
City Milwaukie	State OR	Zip 97222
Latitude 45.43643	Longitude 122.60085	
Tracking Code RVS in 2006	Inspection Date 9/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Linwood Elementary School

Final RVS Score

Final Type	Final Score
W2	3.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Linwood Elementary School

Clac_sch19B

Enrollment 352	Year Built (Field Verified) 1988	Year Built (Alt. Source) 1968	Est. Decade Built 1980
Total Area (square ft) 38622	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW General Site CONN TO A	W Seismic Upgrade SEIS JT TO Y2K SECTION	NE Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries