

Sunrise Middle School

North Clackamas SD 12

Clac_sch25A

Building Type	County		
School	Clackamas		
Street			
14331 Se 132nd			
City	State	Zip	
Clackamas	OR	97015	
Latitude	Longitude		
45.41852	122.52885		
Tracking Code	Inspection Date		
Missed	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sunrise Middle School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1131		1991	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
99366		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions