

Carus School

Canby SD 86

Clac_sch31A

Building Type	County	
School	Clackamas	
Street		
14412 S Carus Rd		
City	State	Zip
Oregon City	OR	97045
Latitude	Longitude	
45.27064	122.57128	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Carus School

Final RVS Score

Final Type	Final Score
W2	3.8

FEMA-154 Collapse Potential

Low (<1%)



Enrollment 441	Year Built (Field Verified) 1960	Year Built (Alt. Source) 1960	Est. Decade Built
Total Area (square ft) 57500	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site		
			
S	General Site	S	General Site
			
S	General Site		
			
S	General Site	S	General Site

