

# Cedar Ridge Middle School

Oregon Trail SD 46

Clac\_sch38A

Building Type		County	
School		Clackamas	
Street			
17225 Smith Ave			
City	State	Zip	
Sandy	OR	97055	
Latitude		Longitude	
45.39875		122.26126	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cedar Ridge Middle School

## Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
422		1955	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
55272	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site