

Mulino Elementary School

Clac_sch52A

Molalla River SD 35

Building Type	County		
School	Clackamas		
Street			
26660 S Hwy 213			
City	State	Zip	
Mulino	OR	97042	
Latitude	Longitude		
45.22048	122.58108		
Tracking Code	Inspection Date		
Previous FEMA-154 Report	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary										
Secondary										
Tertiary										

Mulino Elementary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mulino Elementary School

Clac_sch52A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
301		1952	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
31921	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site

