

# William Knight Elementary School

Canby SD 86

Clac\_sch53A

|                |                 |       |
|----------------|-----------------|-------|
| Building Type  | County          |       |
| School         | Clackamas       |       |
| Street         |                 |       |
| 501 N Grant St |                 |       |
| City           | State           | Zip   |
| Canby          | OR              | 97013 |
| Latitude       | Longitude       |       |
| 45.26539       | 122.69828       |       |
| Tracking Code  | Inspection Date |       |
| Hasenberg 02   | 9/15/2006       |       |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W2   | 3.8         | 0          | 0          | 0        | 0          | -0.4   | 0      | 0      | 3.4       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

William Knight Elementary School

## Final RVS Score


| Final Type | Final Score |
|------------|-------------|
| W2         | 3.4         |

## FEMA-154 Collapse Potential

Low (<1%)

# William Knight Elementary School

Clac\_sch53A

|   |                                     |  |                          |
|---|-------------------------------------|--|--------------------------|
| Enrollment<br>506   | Year Built (Field Verified)<br>1948 | Year Built (Alt. Source)<br>1948   | Est. Decade Built        |
| Total Area (square ft)<br>66414   | Number of Stories<br>1              | Basement   | Pounding Potential<br>No |
| Plan Irregularities   |                                     | Vertical Irregularities  |                          |
|   |                                     |  |                          |
|   |                                     |  |                          |
|   |                                     |  |                          |
| Falling Hazards   |                                     | Poor Conditions  |                          |
|   |                                     |  |                          |
|   |                                     |  |                          |
|   |                                     |  |                          |
|     |                                     |  |                          |
| S   | General Site                        | S  | General Site             |
|   |                                     |  |                          |
| S   | General Site                        | S  | General Site             |
|  |                                     |  |                          |
| S   | General Site                        | S  | General Site             |
|  |                                     |  |                          |
| S   | General Site                        | S  | General Site             |
|  |                                     |  |                          |
| S   | General Site                        | S  | General Site             |



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# William Knight Elementary School

Clac\_sch53A



S General Site



S General Site