

# Ackerman Middle School

Canby SD 86

Clac\_sch54A

Building Type	County
School	Clackamas
Street	
350 Se 13Th Ave	
City	State Zip
Canby	OR 97013
Latitude	Longitude
45.25275	122.6842
Tracking Code	Inspection Date
Hasenberg 02	9/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ackerman Middle School

## Final RVS Score

Final Type	Final Score
W2	3.4

## FEMA-154 Collapse Potential

Low (<1%)

# Ackerman Middle School

Clac\_sch54A

Enrollment 956	Year Built (Field Verified) 1970	Year Built (Alt. Source) 1970	Est. Decade Built
Total Area (square ft) 100500	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ackerman Middle School

Clac\_sch54A

