

Howard Eccles Elementary School

Canby SD 86

Clac_sch55A

Building Type	County	
School	Clackamas	
Street		
562 Nw 5th Ave		
City	State	Zip
Canby	OR	97013
Latitude	Longitude	
45.26415	122.70171	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Howard Eccles Elementary School

Final RVS Score

Final Type	Final Score
W2	3.4

FEMA-154 Collapse Potential

Low (<1%)

Howard Eccles Elementary School

Clac_sch55A

Enrollment 420	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built
Total Area (square ft) 57632	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Howard Eccles Elementary School

Clac_sch55A



S General Site



S General Site



S General Site