

Redland Elementary School

Oregon City SD 62

Clac_sch65A

Building Type	County	
School	Clackamas	
Street		
18131 S Redland Rd		
City	State	Zip
Oregon City	OR	97045
Latitude	Longitude	
45.3457	122.49225	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Redland Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)

Redland Elementary School

Clac_sch65A

Enrollment 583	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built
Total Area (square ft) 55000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries