

Sandy High School - Frazier

Oregon Trail SD 46

Clac_sch67A

Building Type	County		
School	Clackamas		
Street			
17100 Bluff Rd			
City	State	Zip	
Sandy	OR	97055	
Latitude	Longitude		
45.40003	122.26946		
Tracking Code	Inspection Date		
Previous FEMA-154 Report	9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8		-0.5	-0.2		-0.8			
Secondary										
Tertiary										

Sandy High School - Frazier

Final RVS Score

Final Type

Final Score

W2

3.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sandy High School - Frazier

Clac_sch67A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1415		1969	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
16048	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



Oregon Trail SD 46

Clac_sch67B

Building Type	County	
School	Clackamas	
Street		
17100 Bluff Rd		
City	State	Zip
Sandy	OR	97055
Latitude	Longitude	
45.40003	122.26946	
Tracking Code	Inspection Date	
Previous FEMA-154 Report	7/28/2006	

[illegible]

OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1415		1937	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
121666	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

Oregon Trail SD 46

[illegible]

OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1415		1923	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
16600	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

