

Mount Scott Elementary School

North Clackamas SD 12

Clac_sch70A

Building Type School	County Clackamas	
Street 11201 SE Stevens Rd		
City Portland	State OR	Zip 97266
Latitude 45.44241	Longitude 122.56464	
Tracking Code RVS in 2006	Inspection Date 9/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Mount Scott Elementary School

Final RVS Score

Final Type	Final Score
W2	3.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Mount Scott Elementary School

Clac_sch70A

Enrollment 470	Year Built (Field Verified) 1989	Year Built (Alt. Source) 1989	Est. Decade Built 1980
Total Area (square ft) 48730	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Building On Hill or Sloped Site	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Steps in Elevation View: 2 to 3 Changes	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



NE Building Name



NE Field Verified Year Built
1989



SE Elevation View



SE Plan Irregularity Primary



SE Vertical Irregularity Tertiary



SE Vertical Irregularity Secondary



SW Plan Irregularity Primary



NW Vertical Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mount Scott Elementary School

North Clackamas SD 12

Clac_sch70B

Building Type School	County Clackamas	
Street 11201 SE Stevens Rd		
City Portland	State OR	Zip 97266
Latitude 45.44296	Longitude 122.56488	
Tracking Code RVS in 2006	Inspection Date 9/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Mount Scott Elementary School

Final RVS Score

Final Type	Final Score
W2	5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Mount Scott Elementary School

Clac_sch70B

Enrollment 181	Year Built (Field Verified) 1991	Year Built (Alt. Source) 1989	Est. Decade Built 1990
Total Area (square ft) 48730	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
NW Vertical Irregularity Secondary CONN TO A		SW Falling Hazard	
		N Plan Irregularity Primary	
		NE Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries