

Boeckman Creek Primary School

West Linn-Wilsonville SD 3J

Clac_sch71A

Building Type	County	
School	Clackamas	
Street		
6700 Sw Wilsonville Rd		
City	State	Zip
Wilsonville	OR	97070
Latitude	Longitude	
45.30921	122.74522	
Tracking Code	Inspection Date	
Missed	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Boeckman Creek Primary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
583		1989	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71222		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions