

Cecile Trost Elementary School

Canby SD 86

Clac_sch76A

Building Type	County
School	Clackamas
Street	
800 S Redwood	
City	State Zip
Canby	OR 97013
Latitude	Longitude
45.25655	122.67492
Tracking Code	Inspection Date
Hasenberg 02	9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3	0	0	0	0	-0.4	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cecile Trost Elementary School

Final RVS Score

Final Type	Final Score
S2	2.6

FEMA-154 Collapse Potential

Low (<1%)

Cecile Trost Elementary School

Clac_sch76A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
611		1993	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
65740	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries