

Spring Mountain Elementary School

North Clackamas SD 12

Clac_sch80A

Building Type	County	
School	Clackamas	
Street		
11645 Se Masa Ln		
City	State	Zip
Portland	OR	97236
Latitude	Longitude	
45.43704	122.53479	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	0	2.4	-0.4	0	0	4.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Spring Mountain Elementary School

Final RVS Score

Final Type

Final Score

C2

4.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
618		2000	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
83000	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions