

# Boones Ferry Primary School

West Linn-Wilsonville SD 3J

Clac\_sch84A

Building Type	County		
School	Clackamas		
Street			
11495 Wilsonville Rd			
City	State	Zip	
Wilsonville	OR	97070	
Latitude	Longitude		
45.30022	122.79519		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Boones Ferry Primary School

## Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
760		2001	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
76000		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions