

Cedaroak Park Primary School

West Linn-Wilsonville SD 3J

Clac_sch85A

Building Type	County	
School	Clackamas	
Street		
4515 S Cedaroak Dr		
City	State	Zip
West Linn	OR	97068
Latitude	Longitude	
45.38881	122.63369	
Tracking Code	Inspection Date	
Missed	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cedaroak Park Primary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
390		1958	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
0		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions