

Campbell Elementary School

Clac_sch87A

North Clackamas SD 12

Building Type	County	
School	Clackamas	
Street		
11326 SE 47th Ave		
City	State	Zip
Milwaukie	OR	97222
Latitude	Longitude	
45.4407	122.61431	
Tracking Code	Inspection Date	
RVS in 2006	9/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Campbell Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Campbell Elementary School

Clac_sch87A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built				
336	1956	1956	1950				
Total Area (square ft)	Number of Stories	Basement	Pounding Potential				
37939	2	No	No				
Plan Irregularities		Vertical Irregularities					
Reentrant Corners: Other		Building On Hill or Sloped Site					
None		Steps in Elevation View: Very Irregular Changes					
None		None					
Falling Hazards		Poor Conditions					
Other: Ornamental Hazard Over Exit		None					
None		None					
None		None					
			NW Elevation View	W Plan Irregularity Primary	W Secondary Structural Type	BRICK WALLS GO THRU	
			W Secondary Structural Type	SW Number of Stories	S Primary Structural Type	ORIG GYM FLOOR PRECST UNITS	
			SW Secondary Structural Type	CMU WALL BELOW	SE Vertical Irregularity Primary	W General Site	2001 GYM



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Campbell Elementary School

North Clackamas SD 12

Clac_sch87B

Building Type	County
School	Clackamas
Street	
11326 SE 47th Ave	
City	State Zip
Milwaukie	OR 97222
Latitude	Longitude
45.44035	122.61394
Tracking Code	Inspection Date
RVS in 2006	9/25/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Secondary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Tertiary		0	0	0	0	0	0	0	0	0

Campbell Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Campbell Elementary School

Clac_sch87B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built					
336	1956	1956	1950					
Total Area (square ft)	Number of Stories	Basement	Pounding Potential					
37939	1	No	Yes					
Plan Irregularities		Vertical Irregularities						
Reentrant Corners: Other		None						
Torsion: Eccentric Stiffness		None						
None		None						
Falling Hazards		Poor Conditions						
Other: General		None						
None		None						
None		None						
								
E Elevation View	S Pounding Potential	SW Pounding Potential	UNIT C	UNIT C	UNIT B			
			NE Plan Irregularity Primary	NE Elevation View	NW Falling Hazard	UNIT B	UNIT D	UNIT D
			SW Plan Irregularity Primary	N Plan Irregularity Primary	NW Falling Hazard	UNIT D	UNIT E	UNIT E



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Campbell Elementary School

Clac_sch87B



W Primary Structural Type
UNIT E - OLD EXT WALL AND NEW ADDN FRAMING



SW Elevation View
UNIT E



NW Plan Irregularity Primary
UNIT F



NE Elevation View
UNIT F



SE Plan Irregularity Primary
UNIT F