

Stafford Primary School

Clac_sch93A

West Linn-Wilsonville SD 3J

Building Type		County	
School		Clackamas	
Street			
19875 Sw Stafford Rd			
City	State	Zip	
West Linn	OR	97068	
Latitude		Longitude	
45.37761		122.70266	
Tracking Code		Inspection Date	
RVS in 2006		12/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Stafford Primary School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
577		1967	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71407	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
None	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



N Primary Structural Type



NE Plan Irregularity Primary



N Vertical Irregularity Secondary



SE Secondary Structural Type



SE Vertical Irregularity Primary



S Plan Irregularity Primary



W Falling Hazard



NW Primary Structural Type

