

New Urban High School

North Clackamas SD 12

Clac_sch94A

Building Type	County	
School	Clackamas	
Street		
1901 SE Oak Grove Blvd		
City	State	Zip
Milwaukie	OR	97267
Latitude		Longitude
45.41721		122.64323
Tracking Code		Inspection Date
RVS in 2006		9/19/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	0	-1	0	-0.4	0	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

New Urban High School

Final RVS Score

Final Type

Final Score

C2

0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

New Urban High School

Clac_sch94A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
277			1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Large Diaphragm or Central Opening	Building On Hill or Sloped Site
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



N Falling Hazard



W Elevation View



W Elevation View



W Other



W Vertical Irregularity Secondary



SW Elevation View



S Plan Irregularity Secondary



E Plan Irregularity Secondary



E Plan Irregularity Secondary

New Urban High School

North Clackamas SD 12

Clac_sch94B

Building Type		County	
School		Clackamas	
Street			
1901 SE Oak Grove Blvd			
City	State	Zip	
Milwaukie	OR	97267	
Latitude		Longitude	
45.41781		122.64326	
Tracking Code		Inspection Date	
RVS in 2006		9/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	0	0	-0.4	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

New Urban High School

Final RVS Score

Final Type

Final Score

W2

1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
277			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Elevation View





NW Falling Hazard
part 3 and 4

