

Colton Middle School

Colton SD 53

Clac_sch96A

Building Type	County		
School	Clackamas		
Street			
21580 S Schieffer Rd			
City	State	Zip	
Colton	OR	97017	
Latitude	Longitude		
45.16553	122.42307		
Tracking Code	Inspection Date		
Hasenberg 02	9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	1.6	-0.8	0	0	5.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Colton Middle School

Final RVS Score

Final Type

Final Score

W2

5.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
181		1994	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
43000	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site