

Sojourner School

North Clackamas SD 12

Clac_sch97A

Building Type		County	
School		Clackamas	
Street			
1905 SE Oak Grove Blvd			
City	State	Zip	
Portland	OR	97267	
Latitude		Longitude	
45.41719		122.64378	
Tracking Code		Inspection Date	
RVS in 2006		9/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sojourner School

Final RVS Score

Final Type

Final Score

C2

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
179			1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Elevation View



SE Falling Hazard



SE Elevation View



E Elevation View



E Elevation View



N Elevation View