

Damascus Middle School

Gresham-Barlow SD 10J

Clac_sch98A

Building Type	County		
School	Clackamas		
Street			
14151 Se 242nd			
City	State	Zip	
Boring	OR	97009	
Latitude	Longitude		
45.4206	122.41438		
Tracking Code	Inspection Date		
Missed	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Damascus Middle School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
362		1929	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
73705		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions