

# Knappa Svensen RFPD

Knappa Fire District

Clat\_fir02A

Building Type Fire - RFPD	County Clatsop	
Street 92768 Keller Rd		
City Knappa	State OR	Zip 97103
Latitude 46.1668	Longitude 123.65723	
Tracking Code RVS in 2006	Inspection Date 9/19/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Knappa Svensen RFPD

## Final RVS Score

Final Type	Final Score
W1	6.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Building Name	S	Primary Structural Type
			
		NE	Elevation View

